






# Inspection Report

<b>Report No:</b> 019871	<b>Manufacturer:</b> not present	
<b>Tag No:</b> n/a	<b>Size:</b> 12x12x11	
<b>Date:</b> 28 November 2023	<b>Type:</b> shootout	
	<b>Serial Number:</b> footy1001	

Automated Test Sheet							
Anchorage		Detail	Totally Enclosed Details		Detail	Additional Details	
Anchor Points	Pass	6	Exits	N/A		Anchor Type	D Ringl
Anchor Accessories	Pass	380/16	Exit Markings	N/A		Number of Anchors	6
<b>Structure</b>			Independent Support	N/A		Open Side Fall-off Height	0.00M
Seam Security	Pass	overlap	Emergency Lighting	N/A		Inside Wall Height	1.8M
Stitching	Pass	3-4mm	Deflation of the User Area	N/A		Play Area	
Blower Tube	Pass	1 - 4	<b>Slides</b>			Max User Height	Max No. Users
Walls & Towers	Pass	less than 5%	Height of Walls	N/A		1.0 metre	N/A
Step/Ramp Size	N/A		Run Out	N/A		1.2 metre	N/A
Grounding	N/A		Clamber Net	N/A		1.5 metre	N/A
Sharp Angles	Pass		Slide Sheet	Pass	gloss sheet	1.8 metre	N/A
Pressure	Pass	ave 5 wg	<b>Blower</b>				
Fall Off Height	N/A		Suitability	Pass		Place of Test	glasgow
Trough Depth	N/A		Inlet and Outlet Mesh	Pass		<b>Notes: this is a shootout and isn't intended on anyone being in or on the inflatable</b>	
Entrapment	N/A		Cable and Plug	Pass			
Stability	Pass		Impeller	Pass			
Deflation/Evacuation	Pass	plus 10	Return Flap	Pass			
Air Loss	Pass		PAT Test	Pass			
Markings	Pass	back	Blower Type	Gibbons			
Identification	Pass	back	Blower Size	1hp			
<b>Materials</b>			<b>Risk Assessment Notes:</b>				
Fabric (Fire)	Pass	tested					
Fabric Strength	Pass	assuming					
Zips	Pass	covered					
Thread	Pass						
Ropes	N/A						
Netting	Pass	2mm					
Windows	N/A						
Artwork	pass	printed					

<h2>Annual Test</h2> <p>I certify that the inflatable play equipment identified by means of the Rpii inspection and the unit complies and in accordance with the European Standard BS EN 14960 and hse 175</p> <h1>PASSED</h1> <p><i>If you suspect that this report is not genuine or has been altered, you can check the equipment's test status by ensuring its been embossed. Please report any irregularities using the contact details below.</i></p>	
---	--

	<b>Report Expiry Date:</b> 27 November2024 <b>Inspection Body:</b> The Bouncy Castle Man <b>Print Name:</b> Mark Eaglesham / rpii no A10179 <b>Signature:</b> 
---	---